

Work Order ID 142027

Tuesday, February 23, 2016 2:25:29 PM

142027

Page 1

Item ID: D350-604-041

Accept

N900040100

Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Rear Locker Extender

Start Date: 2/23/2016 Start Qty: 1.00 ***1***

Cust Item ID:

Required Date: 6/10/2016 Req'd Qty: 1.00 ***1***

Customer:

Reference:

Approvals: Process Plan: MLS Date: FEB 24 2016

Tooling:

Date:

Run Start ***NR1***

QC: _____ Date: _____ SPC (Y/N): _____

Date:

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr	DAS
D2273	<u>K</u> <u>2</u>	10 9-89
D350-604-041	C	

MAY 30 2016

MLS 16-05-30

100 Document Control 0.00

100

DC

DOCUMENT CONTROL

Memo 0.00

Doc.Control -USB or Paperwork

Photocopy bluefile and create labels per PPP D350-604-041
CHG009

DAS
28
9-89

JUN 01 2016

110 PURCHASING 0.00

110

Purchasing

PURCHASING

Memo 0.00

Purchasing

Issue P/O: 31489

Description: D350-604-041 Rear locker extender.

Manufacture as per dwg D2273

Supplier: FDC Composites Inc.

Certification of Conformity and process sheet required.

***EXTREME CARE MUST BE TAKEN TO PROTECT THE SURFACES OF
THE REAR LOCKER. THE SURFACES MUST BE SMOOTH AND FREE
FROM SURFACE DEFECTS SUCH AS SCRATCHES, NICKS, OR
DENTS.***

MUST BE WELL PACKAGE, IF NOT IT WILL BE REFUSE

DAS
13
9-89

1 FEB 25 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	

Root Cause			FAULT CATEGORY			
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐	
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐	
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐	
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐	
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐	
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐	
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐	
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐	
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐	
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐	
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____				
Misidentified ☐	Past Due ☐					

Work Order ID 142027

Tuesday, February 23, 2016 2:25:29 PM

142027

Page 2

Item ID: D350-604-041

Accept

N1900040100Setup Start ***NS1***

Revision ID:

Item Name: Rear Locker Extender

Stop ***NS2***

Start Date: 2/23/2016 Start Qty: 1.00

1

Cust Item ID:

Required Date: 6/10/2016 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start ***NR1***

QC:

Date:

SPC (Y/N):

Date:

Stop ***NR2***Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

120

Receive & Inspect for Damage & Mat'l Certs
Packaging

0.00

120

Packaging

Memo

0.00

Packaging

Ensure a copy of Certification of Conformity and process sheet from Carbon-by-Design is attached.

DO NOT STACK REAR LOCKERS OR ANYTHING ON THEM

130

QC6- Inspect dimensions to drawing

0.00

130

QC

Memo

0.00

Quality Control

Check hole locations to template. DT 8824 Check process sheet and audit.

140

0.00

140

Small Fab

Memo

0.00

Small Fab

1- INSTALL DECALS AS PER DWG

DAS
28
9-89

JUN 01 2016

1X 8016-05-26

① 16-05-27 PD.

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition			
				Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : ☐					

Work Order ID 142027

Tuesday, February 23, 2016 2:25:29 PM

142027

Page 3

Item ID: D350-604-041

Accept

N900040100Setup Start ***NS1***

Revision ID:

Item Name: Rear Locker Extender

Stop ***NS2***

Start Date: 2/23/2016 Start Qty: 1.00

1

Cust Item ID:

Required Date: 6/10/2016 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Run Start ***NR1***Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
150	QC5- Inspect part completeness to step on W/O	0.00							
150									
QC	Memo	0.00							
Quality Control									
									DAS 27 9-89 JUN 01 2016
155	Pick Kit	0.00							
155									
Packaging	Memo	0.00							
Packaging	***DO NOT STACK REAR LOCKERS OR ANYTHING ON THEM***								
									DAS 6 9-89 MAY 30 2016
158	QC4- 100% Inspect kits for completeness	0.00							
158									
QC	Memo	0.00							
Quality Control									
									DAS 28 9-89 JUN 01 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition			
				Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : _____					

Work Order ID 142027

Tuesday, February 23, 2016 2:25:29 PM

142027

Page 4

Item ID: D350-604-041

Accept

N900040100

Setup Start

NS1

Revision ID:

Item Name: Rear Locker Extender

Stop

NS2

Start Date: 2/23/2016 Start Qty: 1.00

1

Cust Item ID:

Required Date: 6/10/2016 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals:

Process Plan: _____

Date: _____

Tooling: _____

Date: _____

Run Start

NR1

QC: _____

Date: _____

SPC (Y/N): _____

Date: _____

Stop

NR2Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

160

160

Packaging

Packaging

0.00

Memo

0.00

DAS
27
9-89DAS
28
9-89

JUN 01 2016

Packaging

Identify and pack for shipping as per PPP D350-604-041

Location:

PPP Rev: Fg 106

170

170

QC

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

Quality Control

JUN 01 2016

MCS

2m 16/06/01

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition			
				Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : ☐					

Picklist Print

Tuesday, February 23, 2016 2:25:34 PM

Page 1

Work Order ID: 142027

142027

Parent Item: D350-604-041

D350-604-041

Parent Item Name: Rear Locker Extender

Start Date: 2/23/2016

Required Date: 6/10/2016

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP Rev:Q03.12.01ReformatKJ/RF IPP REV:R
12.02.07 AS PER ECN12-521 DD verf:JLM IPP REV:S 12.04.04
AS PER DWG REV.B DD VERF:EC IPP REV:T 13.09.12 as per
CHG006/ECN13-616 DDVERF:JLM IPP REV:U 14.05.28 as per
chg008/ecn14-563 DD verf:JLM IPP REV:V 15.03.13 remove cam lock and
washerDD verf:JLM IPP REV:W 15.03.25 ECN15-545 DD VERF:JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

D350-604-041P

Purchased

No

110

Each

0.0000

1

1

D350-604-041P

Rear Locker Extender

**

1X 8016-05-26

D2268

Manufactured

No

140

Each

13.0000

1

1

D2268

Placard

**

141996

DAS
6 27
9-89

Location

Loc Qty

Loc Code

ST006

13

130951

1

132546

12

D2728-1

Manufactured

Yes

140

Each

0.0000

1

1

D2728-1

Dart Logo Label Small

**

DAS
6 27
9-89

D2269

Manufactured

No

155

Each

20.0000

1

1

D2269

Placard

**

Location

Loc Qty

Loc Code

ST006

8

131139

8

ST012a

12

135175

12

DAS
6 27
9-89

MAY 30 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
							Completed By		
							Lead hand / Supervisor Approval Verification		
							QC / QA Coordinator Approval		
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : ☐							
Misidentified ☐	Past Due ☐								

Picklist Print

Tuesday, February 23, 2016 2:25:34 PM

Page 2

Work Order ID: 142027

142027

Parent Item: D350-604-041

D350-604-041

Parent Item Name: Rear Locker Extender

Start Date: 2/23/2016

Required Date: 6/10/2016

Start Qty: 1.00

Required Qty: 1.00

D5062-041

Manufactured No

155

Each

19.0000

1

1

D5062-041

Bracket Assembly

Location

Loc Qty

Loc Code

ST147

19

130525

14

131060

5

DAS
27
9-89

MAY 30 2016

DAS
28
9-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐																																																													
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval																																																									
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval																																																									
Root Cause		FAULT CATEGORY																																																															
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐	Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐	Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐	Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐	Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐	Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐	Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐	Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐	LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐	Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐	Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____			
Misidentified ☐	Past Due ☐																																																																

TABLE 1


POSITION	MATERIALS
1	TOOL SURFACE
2	GELCOAT
3	3/4 oz CHOPPED STRAND MAT
4	7725 FIBER GLASS
5	7725 FIBER GLASS
9	7725 FIBER GLASS
10	PRIMER

TABLE 2

POSITION	MATERIALS
1	TOOL SURFACE
2	GELCOAT
3	3/4 oz CHOPPED STRAND MAT
4	7725 FIBER GLASS
5	7725 FIBER GLASS
6	7725 FIBER GLASS
7	7725 FIBER GLASS
8	7725 FIBER GLASS
9	7725 FIBER GLASS
10	PRIMER

NOTES:

- 1) MATERIAL: SEE TABLE 3
- 2) FINISH: SEE TABLES 1, 2, & 3
ACCEPTABLE TO COVER CRACKS IN GELCOAT BY APPLYING A LAYER OF PPG 6941241A 2C ACRYCOTE WHITE PAINT OVER GELCOAT
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: IDENTIFY PER QSI 044 6.1
- 7) WEIGHT: 5.5- 7.5 lbs
- 8) LAMINATE PER DART QSI 006. LAMINATION SCHEDULE PER THIS DRAWING
- 9) LAYUP USING DT9871 MOLD. WET LAYUP WITH BAG/VACUUM
- 10) TRIM & DRILL PER DT9905. OPEN HOLES TO Ø0.257
- 11) CONSTRUCTION: SEE TABLES 1 & 2
- 12) MATTE TO HOLD DOWN CORNERS AS REQUIRED



D2273 REAR LOCKER EXTENDER

TABLE 3

MATERIAL USED	DESCRIPTION
GELCOAT	POLYCOR 2330PAWK745 (WHITE)
FIBER GLASS MAT	OWENS CORNING 3/4 oz CHOPPED STRAND MAT
FIBER GLASS CLOTH	HEXCEL 7725 FIBER GLASS
RESIN SYSTEM	DION 7704
PRIMER	TEMPO 4500-PB-23G (GREEN)

STOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 142027 MJS
16-02-24

SEE TABLE 1

SEE TABLE 2

SECTION A-A

L	ADD PAINT OPTION (NCR 15-5408)	CP	15.10.19
K	LAYUP AND MATL PER FDC COMPOSITES PROCESS	CP	15.03.12
J	CHANGED GELCOAT TO 4314-001 DURA FR WHITE	ML	13.12.10
I	CHANGE GELCOAT TO POLYCOR 2330PAWK745	SFM	13.08.13
H	CHANGE MATERIAL & MANUFACTURING PROCESS	DC	13.03.15
G	ADD MANUFACTURING OPTION B, ZN BS-1	DC	12.08.08
F	PRIMER LE 3404-S/LE 1175-S WAS 1144-S, ZN A6-1	DC	12.02.27
E	CHANGED SURFACE FINISH FROM 944W005 GELCOAT TO 2330PAWK745 GELCOAT, ZN A7-1. UPDATED DWG TO CURRENT STANDARDS.	DC	12.02.02
D	REMOVE EPOCAST, ADD SURFACE FINISH	CP	02.04.01
C	CLARIFY MATERIAL, LAYUP, AND TOOLING	RF	02.01.30
B	RE-DRAWN	MM	96.05.27
REV.	DESCRIPTION	BY	DATE


DESIGN	JB	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	CP		
CHECKED	AP	DRAWING NO. D2273	REV. 1
MFG. APPR.	JLM	SHEET 1 OF 1	
APPROVED	WM	TITLE 350 REAR LOCKER EXTENDER	
DE APPR.	DS	DATE 15.10.19	

APPROVED

RELEASED
2015-11-03
EN 15-637

COPYRIGHT © 1996 BY DART AEROSPACE LTD
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

ITEM NO.	QTY.	PART NUMBER	DESCRIPTION
	X	D350-604-041	REAR LOCKER EXTENDER ASSEMBLY
1	1	D2268	PLACARD
2	1	D2273	REAR LOCKER EXTENDER
3	4	2600-6	CAMLOCK STUD
4	4	2600-LW	RETAINING WASHER



D350-604-041 REAR LOCKER EXTENDER ASSEMBLY

NOTES:

- 1) MATERIAL: N/A
- 2) FINISH: N/A
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: NONE
- 7) WEIGHT: 5.5 to 7.5 lbs
- 8) INSTALL D2268 PLACARD IN LOCATION SHOWN, CENTERED ON FLANGE

C	REMOVE D2728-1, D2729-1 DECALS (ZN C5-1) REVISED RELATED NOTES, UPDATED PART WEIGHT	ML	13.12.16
B	INCORPORATE DSI 9470 (ZN D7-1), UPDATE DWG TO CURRENT STANDARDS, ADD D2728-1 PLACARD AND ORIENTATION NOTE (ZN C3-1), ADD D2729-1 (ZN C5-1).	DC	12.02.07
A	NEW ISSUE	CP	02.04.01
REV.	DESCRIPTION	BY	DATE
DESIGN	DW	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	ML		
CHECKED	AP	DRAWING NO.	REV. C
MFG. APPR.	JLM	D350-604-041	SHEET 1 OF 1
APPROVED	MP	TITLE	SCALE
DE APPR.	DS	RLE ASSY	NTS
DATE	14.01.02	COPYRIGHT © 2002 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR REPRODUCED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

APPROVED



Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
Tel: 613 632 9577
Fax: 613 632 1053

PURCHASE ORDER

Purchase Order ID **PO31489**

Purchase Order Date 2/25/2016

PO Print Date 2/25/2016

Page Number 6 of

Order From :

VC-FDC01
FDC COMPOSITES INC.
45 CHEMIN DE L'AEROPORT
LOCAL 26
ST-JEAN-SUR-RICHELIEU, QUEBEC J3B 7B5

Ship To : DART AEROSPACE LTD
1270 ABERDEEN
HAWKESBURY, ON K6A 1K7
CANADA

Contact Name
Vendor Phone 450-357-1344 ext303

Ship To Contact
Ship To Phone
Ship Via: Journey Freight collect
Ship Acct:

Buyer Chantal Lavoie
Customer POID
Customer Tax # 10127-2607
Terms Net 30
Currency CAD
FOB Destination-Collect

16 D350-604-041P ✓ Rear Locker Extender 5/12/2016
Yes
5/12/2016

Line Total: \$835.00

AS PER DWG.D2273 REV.L
B142025 ✓

\$835.00 \$835.00

17 D350-604-041P ✓ Rear Locker Extender 6/16/2016
Yes
6/16/2016

Line Total: \$835.00

AS PER DWG.D2273 REV.L
B142026 ✓

\$835.00 \$835.00

18 D350-604-041P ✓ Rear Locker Extender 6/16/2016
Yes
6/16/2016

Line Total: \$835.00

AS PER DWG.D2273 REV.L
B142027 ✓

\$835.00 \$835.00

88/6-5520

Note:

2/25/2016

FDC Composites inc.
45, Chemin de L'Aéroport
Local 26
Saint-Jean-sur-Richelieu (QC)
J3B 7B5 **Tél.:** 450 357-1344

Bon de livraison

19/05/2016

Commande : 2408 Rev. A
Référence : PO #31489/9-20

Client : Dart

DART AEROSPACE
1270 Aberdeen Street
Hawksbury, ON
K6A 1K7

Expédier à

Même

Tél.: 1 613 632-9577

No item	Description	Qté	Qté livrée	Qté B/O
	2016-03-24-3 As per DWG.D2273 Rev .L B142023			
D350-604-041P	REAR LOCKER EXTENDER PO item: 31489/15 2016-03-29-1 As per DWG.D2273 Rev .L B142024	1		
D350-604-041P ✓	REAR LOCKER EXTENDER PO item: 31489/16 2016-03-29-2 As per DWG.D2273 Rev .L B142025 ✓	1 ✓		
D350-604-041P	REAR LOCKER EXTENDER PO item: 31489/17 2016-03-30-1 As per DWG.D2273 Rev .L B142026	1		
D350-604-041P ✓	REAR LOCKER EXTENDER PO item: 31489/18 2016-03-30-2 As per DWG.D2273 Rev .L B142027	1		
D350-604-041P	REAR LOCKER EXTENDER PO item: 31489/19 2016-03-31-1 As per DWG.D2273 Rev .L	1		

Sp/6-05-26

*** Suite autre page ***



©The information in this document is FDC (Flight Dynamics Corp.) Proprietary Information and is disclosed in confidence. If you are not the intended recipient you are hereby notified that any disclosure, copying, distribution or use of any of the information contained in or attached to this transmission is STRICTLY PROHIBITED.

CERTIFICATE of CONFORMITY

Customer Name: Dart Aerospace.

Customer P/O Number: 31489

Rev. NC


<u>PO Item</u>	<u>Qty</u>	<u>Part number</u>	<u>Dwg number</u>	<u>Description</u>	<u>Dart ID</u>	<u>FDC ID</u>	<u>Lot</u>
9	1	D350-604-041P	D2273 Rev L	350 Rear Locker Extender	B142018	DAE001-074	2016-03-11
10	1	D350-604-041P	D2273 Rev L	350 Rear Locker Extender	B142019	DAE001-075	2016-03-23-1
11	1	D350-604-041P	D2273 Rev L	350 Rear Locker Extender	B142020	DAE001-076	2016-03-23-2
12	1	D350-604-041P	D2273 Rev L	350 Rear Locker Extender	B142021	DAE001-077	2016-03-24-1
13	1	D350-604-041P	D2273 Rev L	350 Rear Locker Extender	B142022	DAE001-078	2016-03-24-2
14	1	D350-604-041P	D2273 Rev L	350 Rear Locker Extender	B142023	DAE001-079	2016-03-24-3
15	1	D350-604-041P	D2273 Rev L	350 Rear Locker Extender	B142024	DAE001-080	2016-03-29-1
16	1	D350-604-041P	D2273 Rev L	350 Rear Locker Extender	B142025	DAE001-081	2016-03-29-2
17	1	D350-604-041P	D2273 Rev L	350 Rear Locker Extender	B142026	DAE001-082	2016-03-30-1
18	1	D350-604-041P	D2273 Rev L	350 Rear Locker Extender	B142027	DAE001-083	2016-03-30-2
19	1	D350-604-041P	D2273 Rev L	350 Rear Locker Extender	B142028	DAE001-084	2016-03-31-1
20	1	D350-604-041P	D2273 Rev L	350 Rear Locker Extender	B142029	DAE001-085	2016-03-31-2

NOTE : Paint process : interior surface re-painting as specified on Darts's PO by sanding gelcoat to remove cracks and application of PPG 6941241A 2C Acrycote White paint Lot 01516. Catalyst was PPG 794002 2C Acrycote Lot 98841.

Catalysed PPG acrycote paint complies with FAR 25.853 Appendix F Part I (b)-Par.4 (Vertical Test 60 seconds).

I hereby certify that the workmanship, material and the processes used in the manufacture of the above part(s) supplied are in accordance with the requirements of the applicable Purchase Order.

Signature:


Jules Fournier, BDI, Quality Manager

Date: 2016-03-31